




Technical Service Bulletin

SUBJECT: ABS interface availability

Products Affected: All versions of ABS interface JC24XXXX (12 and 24 volts)

Effective Date: June 2011

Telma is committed to a philosophy of continuous improvement as a way of enhancing the end-user's experience with our product.



The Telma ABS interface has been phased out of our current product range and is no longer available.

A new product called the Telma Control Module (TRCM) (part number TIG31062) has been introduced and is now available as an alternative to the ABS interface.

TRCM has all the functionality of the ABS interface but with modernized architecture and added features such as PC interface for diagnostics and configuration as well as the ability to obtain speed, ABS, and other information by listening to the vehicle CAN bus.

Refer to service bulletin TL105087 for more details about this new product introduction and document TL105088 for the complete product profile.

A conversion harness (part number TID11044) is available for installation of the TRCM on a vehicle in the field if it becomes necessary to replace the ABS Interface.

If you have any questions, contact Telma customer support at 800 797-7714, go to the Telma Web site at www.telmausa.com, or send an email to engineering@telmacse.com with your questions 24 hours a day / 7 days a week.

This document is the exclusive property of TELMA RETARDER INC. It cannot be copied, modified, forwarded, or given to any third party without prior agreement from TELMA RETARDER INC. Any infringement will immediately involve legal action.